

BANGOR

MARINA

Notice to Mariners

No 9 of 2022

Eisenhower Pier Navigational Beacon - ISO R 12S 9M

In Position 54° 40' 1.92" N 5° 40' 19.56" W



Mariners are advised that this aid to navigation is not displaying the correct characteristics i.e. it is **NOT** displaying isophase 12 seconds.

This fault will be repaired or the light will be replaced as soon as possible.

Kevin Baird

Harbour Master (Bangor) Issued: Friday 30th December 2022