

Notice to Mariners

No 11 of 2025

Commercial Pier – Berthing Restrictions and Fendering Defect

Mariners are advised that vessels are not permitted to berth at the outer end of the Commercial Pier, specifically the section protected by Armco barriers. This area is not authorised for berthing at any time.



Commercial operators should also note that an upper section of a fendering unit on the Commercial Pier is missing. Please exercise caution when operating alongside this part of the pier.

These restrictions will remain in place until repair works have been completed.

Thank you for your cooperation.

Kevin Baird

Kevin Baird

Harbour Master (Bangor)